

Regulatory Perspective on Risk Assessments



James M. Hotinger, PE
Assistant Director
Division of Utility and Railroad Safety

Risk Assessment

Assessing risks for a pipeline requires a comprehensive knowledge of the characteristics of each of the piping systems an operator has.

Historical Risk Assessment

- Prior to the Integrity Management Regulations (IMP), risk assessment was mostly just a review of leak repairs.
- Based on this review, decisions were made as to what pipe needed replacement.
- Little consideration for risk, such as population density, was given.

Historical Virginia Activities

Findings:

Inspections of a new transmission pipeline in CY2000 revealed the coating at the joints was not being installed properly. More than 600 joints were involved.

Commission Action:

Company was required to run a high resolution in-line inspection device at 5 and 10 years. A minimum of 10 joints had to be excavated and examined for the first 10 years of operation. Based upon the results of the examination, additional measures may be required.

Historical Risk Assessment

- With the onset of IMP, companies began to develop risk ranking programs.
- Many companies felt that corrosion was their only threat and placed corrosion managers in charge of the integrity management program.
- While corrosion risks were addressed, other risks, such as dents or gouges, were overlooked.


Coating Installed Incorrectly



Corrosion Pits from Poor Coating



Gouge on a 16-inch, 1200 PSI MAOP Transmission Pipeline



Company Crew Damaged a Transmission Pipeline during Excavation




Post IMP Virginia Activities

- Subsequent to the promulgation of the IMP rule, we completed the Gas Integrity Protocol Review of the four intrastate companies with transmission pipelines.
- Conducted field audits of ECDA digs, ICDA digs, and LI digs.
- Observed more than 100 integrity management digs over 2 years.

Location Question


Sch. Date: 11/19/2009
 Inspector: John Land Walter
 Location: Cromwell Road
 Line Number: Joint Use Pipeline
 Chainage: 1. 44 from Launcher
 Absolute Odomet: 1 99099 ; 13676
 Division/District: Manover
 State/Country: Virginia

(2) Pipe Data Diameter: <u>24 inches</u> Wall Thickness: <u>.375 inch</u> Grade: <u>X60</u> Pipe Manufacturer: <u>ACIPCO</u> Longitudinal Seam Weld: <u>ERW</u> MAOP: <u>1250 PSI</u>	(3) External Coating: Coated <input checked="" type="checkbox"/> Uncoated <input type="checkbox"/> Coating Type: <u>FBE</u> Outer Wrap: _____ Total Thickness: _____ Internal Coating: _____ Note: Coating type: asphalt, coal tar, FBE, extruded polyethylene, urethane, tape (single or double wrap), liquid epoxy, other)	(4) Condition of coating and pipe (include % values): Coating: <u>Good</u> Bonding/Adhesion: <u>Good</u> Moisture: <u>Y</u> <u>N</u> Moisture pH: _____ Holidays: <u>Three small holidays</u>
--	---	---



Incorrect Data Recorded

Records Issue – Anomaly Excavated Twice



LOC. 903

DIG #260 04LN. 32"

ST. #6863+65 M/P 170.31

ODA #899260.65

ASE 5867

9-2-99

Newly Identified Areas



Other Inspection Findings

- Inadequate IMP programs
 - Did not bring together all the data needed to properly assess
 - Operators did not identify all of the threats to their facilities
 - Repair procedures were improper or did not address all threats

Construction Practices

- Successful IM programs should identify most faulty construction practices
- More time spent during construction to get it right the first time should eliminate the need for future repairs

Dent from Resting on Rock



Duct Tape under Coating



Jeeping during Installation



We used to think transmission pipelines were away from populated areas



Appomattox, Virginia






Distribution Integrity Management


Data Accuracy

- Accurate and detailed data is crucial to the effectiveness of TIMP and DIMP
- Accuracy starts in the field
- Must have quality assurance to ensure accuracy
- Bad data is counterproductive and a waste of resources.

Statewide Corrosion Leaks by Material (Accuracy of Data)



2010 Gas Damage Cause Distribution



Operator Failures



No Failure



Failure to Call




Failure to Respect the Marks



Other Excavator Failure

Trenchless Excavation around Sewer Laterals





Actions to Mitigate Risk

- Amended Virginia 1-Call Law to address marking of sewer laterals
- Amended Virginia Building Code to require trace wire on all new sewer laterals
- Educated plumbers to call for marking of utilities before attempting to unclog blocked sewer laterals

Done properly, risk assessments, whether TIMP or DIMP, provide operators and regulators the opportunity to ensure the issues from the past are found and corrected. Proper design, construction, and operation of pipelines should prevent these same issues from arising on pipelines built in the future.