



U.S. Department
of Transportation

**Pipeline and
Hazardous Materials Safety
Administration**

233 Peachtree Street Ste. 600
Atlanta, GA 30303

**NOTICE OF PROBABLE VIOLATION
and
PROPOSED COMPLIANCE ORDER**

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

October 25, 2013

Mr. Connell R. Rader
President
Enmark Energy, Inc.
104 First Choice Drive, Suite A
Madison, MS 39110

CPF 2-2013-6011

Dear Mr. Rader:

On August 16, 2013, representatives of the Pipeline and Hazardous Materials Safety Administration (PHMSA), Southern Region, Office of Pipeline Safety (OPS) inspected the records for Enmark Energy, Inc. (Enmark) Rentech 6-inch Pipeline¹ natural gas pipeline facilities in Louisiana and Mississippi, pursuant to Chapter 601 of 49 United States Code.

As a result of the inspection, it appears that Enmark has committed probable violations of the Pipeline Safety Regulations, Title 49, Code of Federal Regulations. The items inspected and the probable violations are as follows:

- 1. §192.465 External corrosion control: Monitoring.
... (d) Each operator shall take prompt remedial action to correct any deficiencies indicated by the monitoring.**

Enmark did not take prompt remedial action to correct deficiencies identified in its annual external corrosion control program monitoring in 2010, 2011, and 2012.

During its 2010 annual external corrosion control program monitoring, Enmark identified inadequate pipe-to-soil (p/s) readings at its cathodic protection test stations at mile posts 15.5 and 17.7 but did not take any corrective actions. Enmark identified similar

¹ Previously called the Lake St. John Gas Line and International Paper 6" Pipeline.