



3408 International Way • Fairbanks, Alaska 99701-7382 • (907) 452-7111 • FAX (907) 457-8111

October 5, 2017

Ms. Kim West
Acting Director, Western Region
Pipeline Hazardous Material Safety Administration
12300 W. Dakota Ave., Suite 110
Lakewood, CO 80228

CPF 5-2017-3003W

Dear Ms. West

Titan Alaska LNG, LLC (Titan) provides the following in response to PHMSA Warning Letter referenced above.

1. §193.2637 Remedial measures.

Prompt corrective or remedial action must be taken whenever an operator learns by inspection or otherwise that atmospheric, external, or internal corrosion is not controlled as required by this subpart.

Coffman engineering recommended in reports dated 2015 and 2016 that pipeline supports and pipeline isolation be installed to prevent corrosion of the carrier pipe. The pipeline rests on support members which are not isolated with a dielectric pad, this has caused external corrosion at several locations on the underside of the pipeline, at the 6 o'clock position. Coffman Engineering made note of this during their audits, but Titan, has yet to remedy. Additionally no record of the repair was made available at the time of the inspection.

Response

Titan has purchased and is installing isolation pads suitable for the purpose of rectifying the isolation issue mentioned above. Additionally Titan is removing any corrosion found in these areas and recoating the pipe before installing the new isolation pads.

Sincerely,

James Branch, Plant Manager
Titan Alaska LNG, LLC