



MPLX LP
1515 Arapahoe Street,
Tower 1, Suite 1600
Denver, CO 80202

August 4, 2023

Via E-mail (robert.burrough@dot.gov)

Mr. Robert Burrough, Director, Eastern Region
Pipeline and Hazardous Materials Safety
Administration 840 Bear Tavern Road, Suite 300
West Trenton, NJ 08628

CPF 1-2023-031-NOA

Dear Mr. Burrough:

Following our call on Tuesday, August 1st and subsequent correspondence between MPLX and PHMSA, we are submitting the following revisions to MPLX's OME:

2. *MPLX's procedures failed to include processes for taking necessary action, such as an emergency shutdown or pressure reduction, to minimize the volume released from any section of a pipeline system in the event of a failure, in accordance with § 195.402(e)(4). MPLX must revise its procedures to address this requirement.*

MPLX has updated Liquid OME Section 7.17.4 to reflect the requested reference of Table 7.16.1. Please see **Attachment 1** for updates.

3. *MPLX failed to include instructions in its written procedures for personnel to recognize conditions that potentially may be safety-related conditions in accordance with § 195.402(f). MPLX must revise its procedures to address this requirement.*

MPLX has updated Liquid OME Section 7.17.11 to reflect the requested reference of Table 7.16.1. Please see **Attachment 2** for updates.

We understand with this submission, PHMSA will issue a closure letter for the above referenced NOA. Subject to that understanding, MPLX withdraws its request for hearing.

As always, we appreciate the opportunity to work with PHMSA in furtherance of our shared goal of pipeline safety. If you have any questions, please don't hesitate to contact me at (303) 531-9529.

Sincerely,

Tony Minutillo

Tony Minutillo MPLX LP
Compliance Manager

Enclosure(s)