



**BUCKEYE PARTNERS, L.P.**

---

Thomas S. (Scott) Collier  
Vice President, Performance Assurance  
(610) 904-4922  
E-Mail: tcollier@buckeye.com

Five TEK Park  
9999 Hamilton Blvd.  
Breinigsville, PA 18031

October 12, 2015

RECEIVED OCT 13 2015

CW

Mr. Byron Coy  
Director, Eastern Region  
Pipeline and Hazardous Materials Safety Administration  
U.S. Department of Transportation  
820 Bear Tavern Road, Suite 103  
West Trenton, NJ 08628

RE: CPF 1-2015-5016M Notice of Amendment: External Corrosion Procedure A-02

Dear Mr. Coy:

Upon review of the above referenced Notice of Amendment (NOA) received on September 15, 2015 from the Pipeline and Hazardous Materials Safety Administration relating to the findings from the July 15 to July 19, 2013 inspection in Breinigsville PA, Buckeye does not contest this NOA.

Buckeye recognizes the deficiency in its Corrosion manual as indicated in the NOA. We are currently drafting a revision to External Corrosion Procedure A-02 to address interference currents including AC which will be submitted to your attention for approval within the required timeframe specified in the NOA. The procedure will identify the necessary criteria and associated actions and timeframes as necessary when criteria are exceeded. Please feel free to contact me or Claudia Pankowski, Director, Regulatory Compliance at 610-904-4113 if you have any questions.

Sincerely,

Thomas S. (Scott) Collier  
Vice President, Performance Assurance

cc: C. Ostach  
C. Pankowski  
M. Shook