



U.S. Department
Of Transportation
Pipeline and
Hazardous Materials
Safety Administration

820 Bear Tavern Road, Suite 103
West Trenton, NJ 08628
609.989.2171

WARNING LETTER

UPS OVERNIGHT DELIVERY

October 18, 2010

Mr. Thomas Wooden
Northern Division Manager
Spectra Energy Corporation
5400 Westheimer Court
Houston, TX 77056

CPF 1-2010-1005W

Dear Mr. Wooden:

On June 22, 2009, a representative of the Pipeline and Hazardous Materials Safety Administration (PHMSA) pursuant to Chapter 601 of 49 United States Code inspected your pipeline facilities in Westwood, Massachusetts.

As a result of the inspection, it appears that you have committed a probable violation of the Pipeline Safety Regulations, Title 49, Code of Federal Regulations. The items inspected and the probable violation(s) are:

1. **§192.709 Transmission lines: Record keeping.**

(c) A record of each patrol, survey, inspection, and test required by subparts L and M of this part must be retained for at least 5 years or until the next patrol, survey, inspection, or test is completed, whichever is longer.