



ENTERPRISE PRODUCTS PARTNERS L.P.  
ENTERPRISE PRODUCTS GP, LLC  
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

January 10, 2013

RECEIVED JAN 15 2013  
*AK*

Pipeline and Hazardous Materials Safety Administration  
U.S. Department of Transportation  
820 Bear Tavern Road, Suite 103  
West Trenton, NJ 08628

Attn: Mr. Byron E. Coy P.E.  
Director, Eastern Region, PHMSA

RE: Response to Notice of Probable Violation and Proposed Civil Penalty  
CPF 1-2012-5022  
P-40 and P-41 inspection between July 12-27, 2011 in Watkins Glen, New York

Dear Mr. Coy:

Enterprise is in receipt of the referenced Notice of Probable Violation (NOPV) and Proposed Civil Penalty (PCP) dated December 18, 2012. This letter serves as Enterprise's response to the NOPV and PCP.

NOPV item #1: *195.579 What must I do to mitigate internal corrosion?*

*(c) Removing Pipe. Whenever you remove pipe from a pipeline, you must inspect the internal surface of the pipe for evidence of corrosion. If you find internal corrosion requiring corrective action under 195.585, you must investigate circumferentially and longitudinally beyond the removed pipe (by visual examination, indirect method, or both to determine whether additional corrosion requiring remedial action exists in the vicinity of the removed pipe.*

Enterprise Response: Though Enterprise does not admit to liability in connection with the alleged violations, in an effort to resolve this matter it has made payment in the amount of \$26,200 on January 3, 2013, via wire 1000373.

Sincerely,

Phu Phan  
Director, Transportation Compliance

cc: Danika Yeager, Regional Director, Operations