



Questar Pipeline Company
Pipeline Compliance – DNR239
PO Box 45360
Salt Lake City, UT 84145-0360
Tel 801 324 3152 • Fax 801 324 3816
troy.sorensen@questar.com

Troy D. Sorensen
Senior Engineer

August 30, 2007

Mr. Rodrick M. Seeley
Director, Southwest Region
Pipeline and Hazardous Materials Safety Administration – Southwest Region
8701 S. Gessner Suite 1110
Houston, TX 77074

RE: O&M Manual Updates – QPC Team O&M Audit May 7, 2007 – May 11, 2007

CPF 4-2007-1009M

Dear Mr. Seeley,

A Notice of Amendment was received by certified mail on July 30, 2007. Attached are the documents that were changed to address the inadequacies found within the Questar Pipeline Operating and Maintenance Procedures Manual. The entire procedure is not attached only the portion that was modified.

Performance Standard Section B - Part 192.745(b)
Standard Practice 3-15-03 - Part 192.227(a)

Performance Standard Section B addresses "prompt action" as well as designation of an "alternate valve."
Standard Practice 3-15-03 addresses the specific API 1104 "Section 6" reference.

In the Notice of Amendment it was requested that each document be sent electronically. As per this request all documents are electronic.

Please contact me if you require additional information.

Respectfully,

Troy D. Sorensen