



U.S. Department
of Transportation

Pipeline and Hazardous Materials
Safety Administration

12300 W. Dakota Ave., Suite 110
Lakewood, CO 80228

NOTICE OF AMENDMENT

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

February 25, 2015

Mr. Rick Weyen
Vice President, Logistics
Tesoro Logistics GP, LLC
19100 Ridgewood Parkway
San Antonio, TX 78259

CPF 5-2015-5005M

Dear Mr. Weyen:

On July 21-24, 2014, a representative of the Pipeline and Hazardous Materials Safety Administration (PHMSA), pursuant to Chapter 601 of 49 United States Code, inspected Tesoro Logistics GP, LLC procedures for the Northwest Products tank facility in Pasco, Washington.

On the basis of the inspection, PHMSA has identified the apparent inadequacy found within Tesoro Logistics GP, LLC plans or procedures, as described below:

1. **§ 195.402 Procedural manual for operations, maintenance, and emergencies.**
 - (c) **Maintenance and normal operations.** The manual required by paragraph (a) of this section must include procedures for the following to provide safety during maintenance and normal operations:
 - (3) **Operating, maintaining, and repairing the pipeline system in accordance with each of the requirements of this subpart and subpart H of this part.**

At the time of the inspection, Tesoro Logistics GP, LLC procedures did not fully address the requirements of Subpart H. Specifically, the procedures did not address § 195.405(a) of Subpart H. Regulation § 195.405(a) states, "After October 2, 2000, protection provided against ignitions arising out of static electricity, lightning, and stray currents during operation and maintenance activities involving aboveground breakout tanks must be in accordance with API Recommended Practice 2003, unless the operator notes in the procedural manual (§ 195.402(c)) why compliance with all or certain provisions of API Recommended Practice 2003 is not necessary for the safety of a particular breakout tank." Tesoro Logistics GP, LLC neither included reference to API Recommended Practice 2003, nor note why compliance with all or certain provisions of API Recommended Practice 2003 is not necessary for the safety of a particular breakout tank or tank farm.


Response to this Notice

This Notice is provided pursuant to 49 U.S.C. § 60108(a) and 49 C.F.R. § 190.237. Enclosed as part of this Notice is a document entitled *Response Options for Pipeline Operators in Compliance Proceedings*. Please refer to this document and note the response options. Be advised that all material you submit in response to this enforcement action is subject to being made publicly available. If you believe that any portion of your responsive material qualifies for confidential treatment under 5 U.S.C. 552(b), along with the complete original document you must provide a second copy of the document with the portions you believe qualify for confidential treatment redacted and an explanation of why you believe the redacted information qualifies for confidential treatment under 5 U.S.C. 552(b). If you do not respond within 30 days of receipt of this Notice, this constitutes a waiver of your right to contest the allegations in this Notice and authorizes the Associate Administrator for Pipeline Safety to find facts as alleged in this Notice without further notice to you and to issue a Final Order.

If, after opportunity for a hearing, your plans or procedures are found inadequate as alleged in this Notice, you may be ordered to amend your plans or procedures to correct the inadequacies (49 C.F.R. § 190.237). If you are not contesting this Notice, we propose that you submit your amended procedures to my office within 30 days of receipt of this Notice. This period may be extended by written request for good cause. Once the inadequacies identified herein have been addressed in your amended procedures, this enforcement action will be closed.

It is requested (not mandated) that Tesoro Logistics GP, LLC maintain documentation of the safety improvement costs associated with fulfilling this Notice of Amendment (preparation/revision of plans, procedures) and submit the total to Chris Hoidal, Director, Western Region, Pipeline and Hazardous Materials Safety Administration. In correspondence concerning this matter, please refer to **CPF 5-2015-5005M** and, for each document you submit, please provide a copy in electronic format whenever possible.

Sincerely,

A handwritten signature in black ink, appearing to read "Chris Hoidal". The signature is fluid and cursive, with the first name "Chris" written in a more compact, looped style and the last name "Hoidal" written in a more extended, flowing style.

Chris Hoidal

Director, Western Region

Pipeline and Hazardous Materials Safety Administration

Enclosure: *Response Options for Pipeline Operators in Compliance Proceedings*

cc: PHP-60 Compliance Registry
PHP-500 D. Mulligan

Activity #148281 (IO5)