



U.S. Department
Of Transportation
Pipeline and
Hazardous Materials
Safety Administration

820 Bear Tavern Road, Suite 103
West Trenton, NJ 08628
609.989.2171

OVERNIGHT EXPRESS DELIVERY

January 30, 2014

Robert Cooper
Vice President of Engineering
EQT Midstream
625 Liberty Avenue,
Pittsburgh, PA 15222

CPF 1-2013-1017M

Dear Mr. Cooper:

From May to September 2011, representatives from the Pipeline and Hazardous Materials Safety Administration (PHMSA) pursuant to Chapter 601 of 49 United States Code, conducted an on-site pipeline safety inspection of EQT Midstream procedures and records for Operations and Maintenance, as well as Design and Construction, at its headquarter office in Pittsburgh, Pennsylvania, and a portion of its pipeline facilities in Pennsylvania and West Virginia. As a result of the inspection, EQT Midstream was issued a Notice of Amendment on August 20, 2013, which proposed amendment of its procedures.

EQT Midstream submitted its amended procedures on September 16, 2013. My staff reviewed the amended procedures, and it appears that the inadequacies outlined in this Notice of Amendment have been corrected.

This letter is to inform you no further action is necessary and this case is now closed. Thank you for your cooperation.

Sincerely,

Byron Coy, P.E.
Director, Eastern Region
Pipeline and Hazardous Materials Safety Administration