



BUCKEYE PARTNERS, L.P.

Thomas S. (Scott) Collier
Vice President, Performance Assurance
(610) 904-4922
E-Mail: tcollier@buckeye.com

Five TEK Park
9999 Hamilton Blvd.
Breinigsville, PA 18031

May 18, 2016

RECEIVED MAY 19 2016

CN

Mr. Byron Coy
Director, Eastern Region
Pipeline and Hazardous Materials Safety Administration
U. S. Department of Transportation
820 Bear Tavern Road, Suite 103
West Trenton, NJ 08628

RE: CPF 1-2016-5002M Notice of Amendment

Dear Mr. Coy:

Buckeye is in receipt of the referenced Notice of Amendment (NOA) received on April 21, 2016 relating to the inspection of Buckeye Partners, L.P. (Buckeye) Operations and Maintenance procedures that took place in Breinigsville, PA from April 13 through 17, 2015.

Buckeye does not contest the NOA and shall submit the amended sections of F-29 "Damaged or Defective Non-Leaking Pipe" and the Corrosion Control Procedures within 60 days of receipt of this notice. The rectifier and critical bond procedures formerly detailed in Corrosion Manual Section A-02 have been rewritten as part of a comprehensive corrosion manual revision which has addressed the concerns noted in this NOA.

If you have any questions, or need additional information, please feel free to contact myself or Claudia Pankowski, Director, Regulatory Compliance at 610-904-4185.

Sincerely,

Thomas S. (Scott) Collier

cc: C. Ostach
C. Pankowski
M. Shook