



U.S. Department
Of Transportation
**Pipeline and
Hazardous Materials
Safety Administration**

820 Bear Tavern Road, Suite 103
West Trenton, NJ 08628
609.989.2171

Overnight Express Delivery

January 30, 2014

Shawn Patterson
President, Operations and Project Delivery
Columbia Pipeline Group/Columbia Gas Transmission Corporation
1700 MacCorkle Avenue, SE
Charleston, WV 25314

CPF 1-2013-1011M

Dear Mr. Patterson:

During November 14-18, 2011, representatives from the Pipeline and Hazardous Materials Safety Administration (PHMSA), pursuant to chapter 601 of 49 United States Code inspected NiSource Gas Transmission & Storage's (NiSource) procedures for Control Room Management in Charleston, WV. The NiSource companies that fall under their Control Room Management procedures include: Columbia Gas Transmission Corp (OpID 2616); Columbia Gulf Transmission (OpID 2620) and Crossroads Pipeline (OpID 993). As a result of the inspection, Columbia Gas Transmission Corporation (Columbia) was issued a Notice of Amendment on July 18, 2013, which proposed amendment of its procedures.

Columbia submitted its amended procedures on August 20, 2013 and October 18, 2013. My staff has reviewed the amended procedures. It appears that the inadequacies outlined in this Notice of Amendment have been corrected.

This letter is to inform you that no further action is necessary and this case is now closed. Thank you for your cooperation.

Sincerely,

Byron Coy, P.E.
Director, Eastern Region
Pipeline and Hazardous Materials Safety Administration