



U.S. Department
of Transportation

**Pipeline and
Hazardous Materials
Safety Administration**

840 Bear Tavern Road, Suite 300
West Trenton, NJ 08628
609.771.7800

NOTICE OF AMENDMENT

OVERNIGHT EXPRESS DELIVERY

January 21, 2022

Mr. Matt Ramsey
President and Chief Executive Officer
Trunkline Gas Company
8111 Westchester Drive
Dallas, Texas 75225

CPF 1-2022-007-NOA

Dear Mr. Ramsey:

From June 15, 2021 through June 17, 2021 and on June 24, 2021, representatives of the Pipeline and Hazardous Materials Safety Administration (PHMSA) pursuant to Chapter 601 of 49 United States Code (U.S.C.) inspected Trunkline Gas Company's (TGC) procedures for its Epps Storage Field in West Carroll County, Louisiana.

On the basis of the inspection, PHMSA has identified the apparent inadequacy found within TGC's procedures, as described below:

1. § 192.12 Underground natural gas storage facilities.

(a) ...

(c) *Procedural manuals.* Each operator of a UNGSF must prepare and follow for each facility one or more manuals of written procedures for conducting operations, maintenance, and emergency preparedness and response activities under paragraphs (a) and (b) of this section. Each operator must keep records necessary to administer such procedures and review and update these manuals at intervals not exceeding 15 months, but at least once each calendar year. Each operator must keep the appropriate parts of these manuals accessible at locations where UNGSF work is being performed. Each operator must have written procedures in place before commencing operations

or beginning an activity not yet implemented.

TGC's written procedures for conducting operations and maintenance activities were inadequate to ensure safe operation of a pipeline facility. Specifically, TGC's written procedures did not specify that its operations & maintenance manuals would be reviewed and updated at intervals not to exceed 15 months.

During the inspection, PHMSA reviewed TGC's UNGS O&M Reservoir Plan. Although TGC's procedures required an annual review of the O&M manuals, the procedures did not specify that the review interval would not exceed 15 months, but at least once each calendar year, in accordance with § 192.12(c).

Therefore, TGC's written procedures required by § 192.12(c) were inadequate. TGC must revise its procedures to address the review frequency of its O&M manuals.

Response to this Notice

This Notice is provided pursuant to 49 U.S.C. § 60108(a) and 49 C.F.R. § 190.206. Enclosed as part of this Notice is a document entitled Response Options for Pipeline Operators in Enforcement Proceedings.


Please refer to this document and note the response options. Be advised that all material you submit in response to this enforcement action is subject to being made publicly available. If you believe that any portion of your responsive material qualifies for confidential treatment under 5 U.S.C. 552(b), along with the complete original document you must provide a second copy of the document with the portions you believe qualify for confidential treatment redacted and an explanation of why you believe the redacted information qualifies for confidential treatment under 5 U.S.C. 552(b).

Following the receipt of this Notice, you have 30 days to submit written comments, revised procedures, or a request for a hearing under §190.211. If you do not respond within 30 days of receipt of this Notice, this constitutes a waiver of your right to contest the allegations in this Notice and authorizes the Associate Administrator for Pipeline Safety to find facts as alleged in this Notice without further notice to you and to issue an Order Directing Amendment. If your plans or procedures are found inadequate as alleged in this Notice, you may be ordered to amend your plans or procedures to correct the inadequacies (49 C.F.R. § 190.206). If you are not contesting this Notice, we propose that you submit your amended procedures to my office within 30 days of receipt of this Notice. This period may be extended by written request for good cause. Once the inadequacies identified herein have been addressed in your amended procedures, this enforcement action will be closed.

It is requested (not mandated) that Trunkline Gas Company maintain documentation of the safety improvement costs associated with fulfilling this Notice of Amendment (preparation/revision of plans, procedures) and submit the total to Robert Burrough, Director, Eastern Region, Pipeline and Hazardous Materials Safety Administration, 840 Bear Tavern Road, Suite 300, West Trenton, NJ 08628. In correspondence concerning this matter, please refer to **CPF 1-2022-007-NOA** and, for

each document you submit, please provide a copy in electronic format whenever possible. Smaller files may be emailed to robert.burrough@dot.gov. Larger files should be sent on USB flash drive accompanied by the original paper copy to the Eastern Region Office.

Sincerely,

A handwritten signature in blue ink, appearing to read "Robert Burrough".

Robert Burrough
Director, Eastern Region
Pipeline and Hazardous Materials Safety Administration

Enclosure: Response Options for Pipeline Operators in Enforcement Proceedings