



U.S. Department of Transportation
Pipeline and Hazardous Materials
Safety Administration

8701 S. Gessner, Suite 630
Houston TX 77074

ELECTRONIC MAIL - RETURN RECEIPT REQUESTED

January 26, 2022

George Green
President & Chief Executive Officer
DCP Midstream
370 17th Street
Denver, Colorado 80202

CPF 4-2021-074-NOA

Dear Mr. Green:

On February 22, 2021 through October 1, 2021, a representative from the Pipeline and Hazardous Materials Safety Administration (PHMSA), pursuant to Chapter 601 of 49 United States Code, conducted an inspection of DCP Midstream's Liquid Pipeline Operations & Maintenance Manual for its Marysville Storage Field and Wattenberg Bushton HVL Systems. As a result of the inspection, DCP Midstream was issued a Notice of Amendment on December 20, 2021, which proposed amendments to DCP Midstream's procedures.

DCP Midstream submitted its amended procedures on January 19, 2022. PHMSA staff reviewed the amended procedures and it appears that the inadequacies outlined in this Notice of Amendment have been corrected.

This letter is to inform you no further action is necessary and this case is now closed. Thank you for your cooperation.

Sincerely,

Mary L. McDaniel, P.E.
Director, Southwest Region
Pipeline and Hazardous Materials Safety Administration