



SENT TO COMPLIANCE REGISTRY
Hardcopy Electronically
of Copies 1 / Date 6.30.08
06-30-08P12:40 RCVD

June 25, 2008

CC-1498

CPF 5-2008-0015W

Mr. Chris Hoidal
Director, Western Region
Pipeline and Hazardous Materials Safety Administration
12300 W. Dakota Ave., Suite 110
Lakewood, CO 80228

Reference: CPF 5-2008-0015W

Subject: Response to a DOT "Warning Letter" Concerning Line Marker Letter Size.

Dear Mr. Hoidal:

Mr. Nguyen, of the DOT, conducted an onsite inspection of our pipeline facility from February 19 to February 21, 2008. A result of that inspection was a DOT "Warning Letter" notifying Midway Sunset Cogeneration Company (MSCC) that the lettering on MSCC line markers was not sized per regulation requirements. Please find attached, photos of the new line markers with the correct letter size; MSCC proof of purchase; and photos showing installed markers. MSCC embraces the importance of public safety and, therefore, wishes not only to meet the letter of the law but the overriding intent.

As such, MSCC appreciates the DOT's review of the circumstances and, especially, the DOT's consideration not to conduct additional enforcement action or penalty assessment proceedings at this time. MSCC commends Mr. Nguyen's professional demeanor during the inspection. It proved an excellent opportunity for MSCC's employees to interact with and learn from a knowledgeable, pleasant, DOT representative.

If you have any questions or comments, please email me at GJans@Edisonmission.com; or call me at (661) 768-3000 ext. 3018.

Sincerely,

A handwritten signature in black ink, appearing to read "Greg Jans", with a stylized flourish at the end.

Greg Jans
Plant Manager

KA/ad

Attachments

Cc: File cc-1498
CEC
DOT Form 1
D. Faiella
J. Alvidres
K. Aspinall
R. Smith